



RELEASE NOTES

Release Date: 10/02/2021

PC Link Version: 6.19.105

Firmware Version: 6.19.60

Fixes:

- Made Wall Wetting Compensation hidden when fuel mode is off.
- Increased Overrun Ignition Trim max retard.
- Changed ST185 and ST205 Sample map trigger offset by 360deg.
- Fixed Math Block related exception.

**THE BELOW CHANGES HAVE ALSO BEEN IMPLEMENTED SINCE V6.19.65
(6.19.99 HAS BEEN SUPERCEDED BY 6.19.105 AND IS NO LONGER AVAILABLE
FOR DOWNLOAD).**

New features:

- Added Honda J30A4 trigger mode.
- Added ECUMaster Switch Board CAN files and help.

Changes:

- Changed MX5 VVT mode to only show 1 bank.
- Changed default Subaru V7-10 Trigger 2 Type to Reluctor.
- Changed DI 1 Pull-up to On in the E36 sample maps.
- Fixed pressure calibrations not showing up for AN Temp inputs.

Fixes:

- Fixed incorrect H-Bridge Fault Codes.
- Fixed logging no parameters bug.
- Fixed not starting after stall issue in some vehicles.
- Fixed MultiTooth/Missing 4-1 trigger pattern.
- Fixed Traction Disable Switch Labeling.
- Fixed Cruise Control On Input in Subaru mode issue.
- Fixed first character being lost when searching table axis runtimes.
- Fixed graph view being reset to 0 position on value change.