



RELEASE NOTES

Release Date: 07/06/2022

PC Link Version: 6.22.38

Firmware Version: 6.22.13

IF YOU ARE UPGRADING TO 6.22 FIRMWARE AND ARE USING GEARSHIFT CONTROL YOU WILL NEED TO RE-TUNE YOUR GEARSHIFT CONTROL WITH THE NEW SETUP.

New features:

- Added Daihatsu K3-VE (VVT) trigger mode.
- Added Jeep Cherokee trigger mode.
- Added WRX11 sample maps.
- Added check box in Options->Preferences which when ticked makes search boxes only search on press of the Enter key (instead of searching on every new character), this can be useful on slower computers.

Changes:

- Made 'Air per Cylinder Estimated' and 'Fuel per Cylinder' runtime values show zero when engine Speed is zero.
- Increased maximum value for Injector Flow Rate settings.

Fixes:

- Fixed AntiLag setting Throttle position to 0% issue.
- Fixed decimal places on runtimes when opening just a log on a fresh PCLink.
- Fixed Gear Lever Force Analog source from being cleared on PCLink connect in some situations.
- Fixed CAN Id being changed when selecting a channel with a standard Id after selecting a channel with an Extended Id over 2047.
- Fixed corrupted sample maps.