



Link Engine Management PC Link Updates

Released July 2019

G4+ Firmware Version 5.6.7.3630 – 27-06-19

New Features

- Trigger modes for Dodge Hemi 60-2 crank and Jeep Cherokee 2000.
- External 2k7 pull up resistor option to ANTemps.

Changes

- VVT position calculation works when the gap between teeth is less than the CAM Tooth Tolerance.
- Improvements to Limits.
- Improvements to idle speed control when no speed sensor is selected.

Fixes

- Ford Coyote trigger mode syncs to engine correctly.
- Charge temperature calculation handles negative temperatures correctly.
- Knock control for single rotor rotary engine.
- CAN calculates signed integers correctly.
- Idle speed control gain tables.